Problem M3

Draw loading, shear and bending moment diagrams for the following beam under the

loading shown. Label all key values (i.e. where changes in magnitude or slope occur).

Maintain the convention shown below for positive shear forces and bending moments:

10 kN   10 kN

5 kN

1m   1m   1m